

Fig. 1

Fig.1




Fig.2




Fig.3

Fig.4




Fig.5




Fig.6






Fig.7



3/79

600 

SETTING THE STAKING MACHINE ~610

STACKING THE FOIL AND THE
CONNECTION MEMBER ~620

STAKING THE FOIL AND THE
CONNECTION MEMBER TOGETHER ~630

Fig.8

4/79




Fig. 9A




Fig. 9B





Fig. 10

5/79

700 

SETTING THE STAKING MACHINE ~710

STACKING THE FOILS ~720

STAKING THE FOILS TOGETHER ~730

Fig.11

6/79




Fig. 12

7/79




Fig.13

8/79




Fig. 14




Fig. 15

9/79




Fig.16

10/79




Fig.17

11/79





Fig.18

12/79






Fig. 20




Fig. 21




Fig. 22




Fig. 23

14/79




Fig. 25




Fig. 27




Fig. 24




Fig. 26

15/79




Fig.28A

16/79




Fig.28B

17/79




Fig. 29

18/79




Fig.30




Fig.31

19/79




Fig.32

20/79




Fig.33




Fig. 34

22/79




Fig.35

23/79




Fig.36




Fig.37

24/79




Fig.38

25/79




Fig. 39




Fig. 40




Fig. 41

27/79






Fig.42





30/79

2024 — A




Fig. 45

31/79




Fig.46

32/79




Fig.47

33/79




Fig.48

34/79




Fig. 49




Fig. 50

35/79




Fig. 51

36/79




Fig. 52




Fig. 53




Fig. 54




Fig. 55

37/79




Fig. 56




Fig. 57

38/79






Fig. 58

39/79





41/79




Fig.61




Fig.62A










Fig.62B

42/79



43/79



44/79




Fig.68




Fig.69

45/79




Fig.70

46/79




Fig.71




Fig.72

47/79




Fig.73




Fig.74

48/79




Fig.75




Fig.76

49/79





Fig.77

50/79



51/79




Fig.79




Fig.80

52/79




Fig.81




Fig.82




Fig. 83A

Fig. 83B

54/79




Fig. 84

55/79




Fig. 85A




Fig. 85B





Fig. 86

57 / 79



58/79




Fig.88




Fig.89

59/79




Fig. 90

60/79




Fig. 91

61/79




Fig.92




Fig. 93

63/79




Fig. 94




Fig. 95

64/79




Fig. 96

65/79





Fig. 97

66/79






Fig. 99










Fig. 100

68/79



69/79





71/79




Fig.105




Fig.106A

72/79




Fig.106B




Fig.106C

73/79




Fig. 106D




Fig. 106E

74/79




Fig.106F

75/79




Fig.107A




Fig.107B

76/79




Fig.108

77/79




FIG. 109




FIG. 110




FIG. 111




FIG. 112




FIG. 113




FIG. 114

79/79




FIG. 115